

## HiOS v07.1.00 released

2019-12-17 - Christoph Strauss - Switches and Router

Software Release 07.1.00

-----

Bugfixes (see Issue List)

New Functions:

- Password change on first login

Protocols that require a login (e.g. SNMPv3) remain deactivated until the password is changed.

Contenido relacionado

- [HAC\\_Issue-List\\_2019-12-17.pdf](#)
- [Web\\_EES\\_07100.zip](#)
- [Web\\_EESX\\_07100.zip](#)
- [Web\\_GRS\\_07100.zip](#)
- [Web\\_MSP\\_07100.zip](#)
- [Web\\_OCTOPUS\\_07100.zip](#)
- [Web\\_RDD\\_07100.zip](#)
- [Web\\_RED\\_07100.zip](#)
- [Web\\_RSP-2A\\_3S\\_07100.zip](#)
- [Web\\_RSP-2S\\_07100.zip](#)
- [Web\\_RSPE\\_07100.zip](#)
- [Web\\_RSPL\\_07100.zip](#)
- [Web\\_RSPS\\_07100.zip](#)